



Tire Size

10.00-20 10.00-20 10.00-20

4245R 4245CAM 2245R 2245CAM 10.00-22 2249R

2249CAM 10.00-22 2452 10.00-22 2849R

10.00-22 11.00-20 11.00-22

11-22.5

11-22.5

11-24.5

11-24.5 11-24.5

11-24.5 112-22.5 12-24.5

295/75 R22.5 305/70 R22.5

275/80 R24.5 285/70 R24.5

315/80 R22.5

Part# 2845R Reinforced Single Serv. Chain 2845CAM Same as above but with CAM Lock

Dual Truck Chain Same as above but with CAM Lock Single Truck Chain

Same as above but with CAM Lock Single Truck Chain Same as above but with CAM Lock

Single Mud Service Chain

Single Mud Service Chain

Dual Triple Reinf.

Single Truck Chain

Single Truck Chain

Single Truck Chain

Dual Triple Reinf.

Single Truck Chain

Single Truck Chain

Single Truck Chain

Single Truck Chain

Reinforced Single Serv. Chain

Same as above but with CAM Lock

Reinforced Single Serv. Chain

Reinforced Single Serv. Chain

Single Mud Service Chain

Single Mud Service Chain

2849CAM 4849R 2452

2255R 2255CAM

2245R 2245CAM

2845R 2845CAM

2249R 2249CAM

2452

2849R 2849CAM

4849R 2452

2255R 2255CAM

2247R 2247R

2247CAM 2255R

2255CAM 2247R 2247R

Same as above but with CAM Lock Single Truck Chain 2247CAM

Single Truck Chain

Same as above but with CAM Lock

\$250.08 \$129.26 \$129.26 \$134.26

Special

\$217.21

\$251,24

\$241.98

\$246.98

\$129.26

\$134.26

\$129.26

\$134.26

\$250.14

\$230.86

\$261.76

\$445.79

\$250.14

\$214.22

\$250.08

\$129.26

\$134.26

\$217.21

\$251.24

\$129.26

\$134.26

\$250.14

\$230.86

\$261.76

\$445.79

\$250.14

\$214.22

\$250.08

\$129.26

\$129.26

\$134.26

\$214.22

irrent manufacturers' pricing and may be withdrawn at any time before the stated expiration date of the promotion.

www.cookbrothersco.com

BINGHAMTON, NY 607-723-7481 • HOMER, NY 607-749-6716 • UTICA, NY 315-733-2595

WATERTOWN, NY 315-788-5977 • ELMIRA, NY 607-796-2651 • ROCHESTER, NY 585-458-1520

CAMP HILL, PA 717-975-8151 • PITTSTON, PA 570-655-9152 • DURYEA, PA 570-609-5294 • SCRANTON, PA 570-342-0208

