



**COOK**  
BROTHERS  
TRUCK PARTS

**2024**



# New Core Free Genuine Meritor Rear Carrier Assemblies



**NEW UNITS**

Part Number	Ratio	Description	Warranty
R61A13200B1978S264SP	264	New Forward Carrier RD20145	3 Years
R61A13200B1978S321SP	321	New Forward Carrier RD20145	3 Years
R61A13200B1978S342SP	342	New Forward Carrier RD20145	3 Years
R61A13200B1978S358SP	358	New Forward Carrier RD20145	3 Years
R61A13200B1978S373SP	373	New Forward Carrier RD20145	3 Years
R61A13200B1978S390SP	390	New Forward Carrier RD20145	3 Years
R61A13200B1978S411SP	411	New Forward Carrier RD20145	3 Years
R61B43200L1676264SP	264	New Rear Rear Carrier RR20145	3 Years
R61B43200L1676321SP	321	New Rear Rear Carrier RR20145	3 Years
R61B43200L1676342SP	342	New Rear Rear Carrier RR20145	3 Years
R61B43200L1676358SP	358	New Rear Rear Carrier RR20145	3 Years
R61B43200L1676373SP	373	New Rear Rear Carrier RR20145	3 Years
R61B43200L1676390SP	390	New Rear Rear Carrier RR20145	3 Years
R61B43200L1676411SP	411	New Rear Rear Carrier RR20145	3 Years
R61A33200K2117S373SP	373	New Forward Carrier RPL23160	3 Years
R61A33200K2117S391SP	391	New Forward Carrier RPL23160	3 Years
R61A33200K2117S410SP	410	New Forward Carrier RPL23160	3 Years
R61A33200K2117S430SP	430	New Forward Carrier RPL23160	3 Years
R61A33200K2117S456SP	456	New Forward Carrier RPL23160	3 Years
R61A33200K2117S489SP	489	New Forward Carrier RPL23160	3 Years
R61A33200K2117S538SP	538	New Forward Carrier RPL23160	3 Years
R61A43200F2138S373SP	373	New Rear Rear Carrier RRL23160	3 Years
R61A43200F2138S391SP	391	New Rear Rear Carrier RRL23160	3 Years
R61A43200F2138S410SP	410	New Rear Rear Carrier RRL23160	3 Years
R61A43200F2138S430SP	430	New Rear Rear Carrier RRL23160	3 Years
R61A43200F2138S456SP	456	New Rear Rear Carrier RRL23160	3 Years
R61A43200F2138S489SP	489	New Rear Rear Carrier RRL23160	3 Years
R61A43200F2138S538SP	538	New Rear Rear Carrier RRL23160	3 Years

**Contact your Cook Brothers Representative for Availability and Pricing.**

Prices listed are based on current manufacturers' pricing and may be withdrawn at any time before the stated expiration date of the promotion.



**COOK**  
BROTHERS  
TRUCK PARTS

**2024**



## New Core Free Genuine Dana Carrier Assemblies



Part Number	Ratio	Description	Axle Splines	Warranty
E16DS404325CF-SP	325	New DS404 Forward Carrier Assembly	41	2 Years
E16DS404336CF-SP	336	New DS404 Forward Carrier Assembly	41	2 Years
E16DS404342CF-SP	342	New DS404 Forward Carrier Assembly	41	2 Years
E16DS404355CF-SP	355	New DS404 Forward Carrier Assembly	41	2 Years
E16DS404370CF-SP	370	New DS404 Forward Carrier Assembly	41	2 Years
E16DS404390CF-SP	390	New DS404 Forward Carrier Assembly	41	2 Years

E16RS404325CF-SP	325	New RS404 Rear Rear Carrier Assembly	41	2 Years
E16RS404336CF-SP	336	New RS404 Rear Rear Carrier Assembly	41	2 Years
E16RS404342CF-SP	342	New RS404 Rear Rear Carrier Assembly	41	2 Years
E16RS404355CF-SP	355	New RS404 Rear Rear Carrier Assembly	41	2 Years
E16RS404370CF-SP	370	New RS404 Rear Rear Carrier Assembly	41	2 Years
E16RS404390CF-SP	390	New RS404 Rear Rear Carrier Assembly	41	2 Years

E16DSP40336CF-SP	336	New DSP40 Forward Carrier Assembly	41	2 Years
E16DSP40342CF-SP	342	New DSP40 Forward Carrier Assembly	41	2 Years
E16DSP40355CF-SP	335	New DSP40 Forward Carrier Assembly	41	2 Years
E16DSP40370CF-SP	370	New DSP40 Forward Carrier Assembly	41	2 Years
E16DSP40390CF-SP	390	New DSP40 Forward Carrier Assembly	41	2 Years



E16RSP40336CF-SP	336	New RSP40 Rear Rear Carrier Assembly	41	2 Years
E16RSP40342CF-SP	342	New RSP40 Rear Rear Carrier Assembly	41	2 Years
E16RSP40355CF-SP	355	New RSP40 Rear Rear Carrier Assembly	41	2 Years
E16RSP40370CF-SP	370	New RSP40 Rear Rear Carrier Assembly	41	2 Years
E16RSP40390CF-SP	390	New RSP40 Rear Rear Carrier Assembly	41	2 Years

E16D170DP373CF-SP	373	New D170DP Forward Carrier Assembly	46	2 Years
E16D170DP391CF-SP	391	New D170DP Forward Carrier Assembly	46	2 Years
E16D170DP410CF-SP	410	New D170DP Forward Carrier Assembly	46	2 Years
E16D170DP430CF-SP	430	New D170DP Forward Carrier Assembly	46	2 Years



E16S170D373CF-SP	373	New S170D Carrier Assembly	46	2 Years
E16S170D391CF-SP	391	New S170D Carrier Assembly	46	2 Years
E16S170D410CF-SP	410	New S170D Carrier Assembly	46	2 Years
E16S170D430CF-SP	430	New S170D Carrier Assembly	46	2 Years
E16S170D456CF-SP	456	New S170D Carrier Assembly	46	2 Years

**Contact your Cook Brothers Representative for Availability and Pricing.**

Prices listed are based on current manufacturers' pricing and may be withdrawn at any time before the stated expiration date of the promotion.