

Make Your Truck Cool Again

Northern Radiator Replacement A/C Condensor





Peterbilt	Description	Special
NR 9260112	Peterbilt 2012 & Newer 579	\$122.57
NR 9240715	08 & Newer 325, 330, 335, 340,365	\$103.42
NR 9246000	95 - 07 357,375,377,378,379,385 Series w/Short Hood	\$130.24
NR 9240702	08 367, 08 & Newer 387	\$112.54
NR 9241414	95 - 07 357,375,377,378,379,385,Series w/Short Hood	\$353.42
NR 9241417	05 - 07 330,335,340,386,387,Series	\$127.39
International / Navister		Special
NR 9260117	18 & Newer LT, RH Series	\$150.06
NR 9279073	07 - 10 4000 Series	\$117.38
NR 9240828	99 - 02 9200,9300,9400 Series	\$148.53
NR 9240541	01 - 07 7300-7700, 9000	\$102.61
NR 9240563	01-07 5500,8600,9200,9400,9600,9900 Series	\$118.60
NR 9240829	01-06 4200,4300,4400,8500 Series	\$113.31
NR 9260122	18 & Newer 4000,7000 Series, HX & MV Series	\$184.74
NR 9240827	93-02 4600,4700,4900 Series w/7.3L Engine	\$186.01

Prices listed are based on current manufacturers' pricing and may be withdrawn at any time before the stated expiration date of the promotion.

www.cookbrothersco.com

BINGHAMTON, NY 607-723-7481

BUFFALO, NY 716-989-3150 • CORTLAND, NY 607-749-6716 • UTICA, NY 315-733-2595 WATERTOWN, NY 315-788-5977 • ELMIRA, NY 607-796-2651 • ROCHESTER, NY 585-458-1520



CAMP HILL, PA 717-975-8151 • PITTSTON, PA 570-655-9152 • DURYEA, PA 570-609-5294 • SCRANTON, PA 570-342-0208







Special





Description

Freightliner





R 9260000 R 9240731 R 9240557	08 & Newer Cascadia, Coronado 07 & Newer Columbia, Coronado, 08 - Newer Sterling	\$125.35
	07 & Newer Columbia, Coronado, 08 - Newer Sterling	
R 9240557	or errors commission, continued, continued commission	\$111.40
1 72 10337	03-07 Business Class M2,106,112, 06 - 07 Century	\$113.25
R 9240607	91-02 FLD112/120 Classic XL	\$103.65
R 9260118	18 & Newer Cascadia	\$151.39
ack		Special
R 9241615	08 May 2016 CHU, CXU, GU	\$124.63
R 9240546	03 - 07 CV613, CV713	\$155.50
R 9240796	07-08 Vision	\$143.86
R 9240568	01-07 CH, CV613, Granite CV713, Vision CV713	\$125.07
R 9241215	94 - 01 CH Series	\$150.15
estern Star		Special
R 9240738	97-08 4900, 5900, 6900, Series	\$146.93
R 9260103	4800.4900,6900 Series	\$155.69
R 9241612	94-04 3700,3800,4800,4900,4900E,4900EX,4900FA	\$296.79
enworth		Special
R 9260112	12- & Newer T680	\$122.57
R 9240702	08 - & Newer T2000	\$112.54
R 9246001	95-07 T400,T600,W900	\$107.89
R 9240732	08- & Newer T660,W900L	\$116.19
R 9240552	96-11 T800, 10-11 W900B	\$132.65
olvo		Special
R 9241615	08 - May 2016 VHD,VNL,VNM	\$124.63
R 9241611	92-98 Conventional Cab Series, WCA & WIA Series (42-62 Models) w/R134A System (Fittings on same side)	\$126.81
R 9241610	94-01 Conv. Cab w/R134A System	\$146.35
	R 9240546 R 9240546 R 9240568 R 9240568 R 9240738 R 9240738 R 9260103 R 9241612 R 9240702 R 9240702 R 9240732 R 9240552 R 9241615 R 9241611	R 9241615 08 May 2016 CHU, CXU, GU R 9240546 03 - 07 CV613, CV713 R 9240796 07-08 Vision R 9240568 01-07 CH, CV613, Granite CV713, Vision CV713 R 9241215 94 - 01 CH Series R 9240738 97-08 4900, 5900, 6900, Series R 9240738 97-08 4900, 5900, 6900, Series R 9240103 4800.4900,6900 Series R 9241612 94-04 3700,3800,4800,4900,4900E,4900EX,4900FA R 9240712 12- & Newer T680 R 9240702 08 - & Newer T2000 R 9240702 08 - & Newer T2000 R 9240703 08- & Newer T660,W900L R 9240732 08- & Newer T660,W900L R 9240552 96-11 T800, 10-11 W900B R 9241615 08 - May 2016 VHD,VNL,VNM R 92-98 Conventional Cab Series, WCA & WIA Series (42-62 Models) w/R134A System (Fittings on same side)